



PLS12 XP1	
1	PA7
2	PA10
3	PA11
4	PA12
5	PA13
6	PA14
7	PA15
8	PA16
9	PA17
10	PA18
11	3V3
12	GNDD

PLS12 XP2	
1	PA19
2	PA20
3	PA21
4	PA22
5	PA25
6	PA26
7	PA27
8	PA28
9	PA29
10	NRST
11	3V3
12	GNDD



www.as-tools.ru